

CERTIFICATE OF COMPLIANCE

Certificate Number E66043
Report Reference E66043-19780714
Issue Date 2020-JANUARY-24

Issued to: IDEC CORP
6-64 NISHIMIYAHARA 2-CHOME
YODOGAWA-KU, OSAKA 532-0004 JAPAN

**This certificate confirms that
representative samples of**

COMPONENT - MOTOR CONTROLLERS, MAGNETIC
Component - Magnetically Operated Motor Controllers,
Model Nos. RR1BA, RR2B, RR2BA, RR3B, RR2P, RR3P,
RR3PA, RR2KP all followed by -U, -US, -USC, UC, -UL, -
USL, -ULC or -USLC, may be followed by E. Model RR1B-
204-1. *Models RR3B-205, -204-1, -204-6

Have been investigated by UL in accordance with the
component requirements in the Standard(s) indicated on
this Certificate. UL Recognized components are incomplete
in certain constructional features or restricted in
performance capabilities and are intended for installation in
complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 60947-1 LOW-VOLTAGE SWITCHGEAR AND CONTROLGEAR
- PART 1: GENERAL RULES and UL 60947-4-1 LOW-VOLTAGE
SWITCHGEAR AND CONTROLGEAR - PART 4-1: CONTACTORS
AND MOTOR-STARTERS - ELECTROMECHANICAL
CONTACTORS AND MOTOR-STARTERS

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

